



MC Switch Module DSub Connectors

Date: 02.03.2015

Solution:

| Module | Terminating Connector | Mating Connector |
|--------|----------------------------|--------------------------|
| MC3120 | DB78 HD connector (Female) | DB78 HD connector (Male) |
| MC132 | “ | “ |
| MC3164 | “ | “ |
| MC3324 | “ | “ |
| MC3416 | “ | “ |
| MC3534 | “ | “ |
| MC3648 | “ | “ |




Figure 1: Example of a DB78 HD connector.



Headquarters

RIGOL TECHNOLOGIES, INC.
No.156,Cai He Village,
Sha He Town,
Chang Ping District, Beijing,
102206 P.R.China
Tel:+86-10-80706688
Fax:+86-10-80705070
Email: support@rigol.com

USA

RIGOL TECHNOLOGIES,USA INC.
102000 SW Allen Blvd, Suite C
Beaverton
OR 97005, USA
Toll free: 877-4-RIGOL-1
Office: (440) 232-4488
Fax: (216)-754-8107
Email: info@rigol.com

EUROPE

RIGOL TECHNOLOGIES GmbH
Lindbergh str. 4
82178 Puchheim
Germany
Tel: 0049- 89/89418950
Email: info-europe@rigoltech.com