

**RIGOL**  
Beyond Measure



## Rigol DM3058 and DM3068 RS-232 Connection

*Date:*04.18.2012

*Solution:* Both DMM's require a Null Modem Cable connection.1

Each line should terminate in a carriage return followed by a line feed ("r/n").

**rigolna.com**

Rigol Technologies USA, Inc.  
Phone/Fax: 440-232-4488

Toll Free: 877-4-RIGOL-1

7401 First Place, Ste. N Oakwood Village, OH 44146 USA