




USB instrumentation: Blue Screen of Death with Win 7 64 bit

Date: 11/14/2011

Solution: In some instances, plugging USB instrumentation can cause a Page Fault Blue Screen (Blue Screen of Death or BSD) with Win 7 64 bit OS'.

See below:





This error can be attributed to the VISA IVI Shared components version compatibility with Win 7 64 bit.

The fix can be found in IVI Shared Components V. 1.4 below.

http://ivifoundation.org/shared_components/Default.aspx

NOTE: VISA IVI Shared components V. 1.4 was not included in National Instruments VISA (NI-VISA) 5.1.1 or earlier and it will need to be added to any system running this version or earlier.