



**How to find the Firmware Revision of the DP1116A/DP1308A Power Supplies**

*Date:* 12.02.2013

*Solution:* Press Utility > Wrench Icon > Right Arrow > Sys Info



## Headquarters

RIGOL TECHNOLOGIES, INC.  
No.156,Cai He Village,  
Sha He Town,  
Chang Ping District, Beijing,  
102206 P.R.China  
Tel:+86-10-80706688  
Fax:+86-10-80705070  
Email: [support@rigol.com](mailto:support@rigol.com)

## USA

RIGOL TECHNOLOGIES,USA INC.  
7401 First Place, Suite N  
Oakwood Village  
OH 44164, USA  
Toll free: 877-4-RIGOL-1  
Office: (440) 232-4488  
Fax: (216)-754-8107  
Email: [info@rigol.com](mailto:info@rigol.com)

## EUROPE

RIGOL TECHNOLOGIES GmbH  
Lindbergh str. 4  
82178 Puchheim  
Germany  
Tel: 0049- 89/89418950  
Email: [info-europe@rigoltech.com](mailto:info-europe@rigoltech.com)