



Douglas Smith's EMC Resources

Date: 07.09.2014

Solution: Here are links to Mr. Douglas Smith's High Frequency Measurements webpage.

These are helpful EMC resources:

Troubleshooting Radiated and Conducted Immunity Problems in the Development Lab

<http://www.emcesd.com/tt2014/tt040114.htm>

Radiated Emissions Can be Strongly Affected by Setup, A Problem for Testing Standards (An Example Using a Class D Stereo Audio Amplifier)

<http://www.emcesd.com/tt2014/tt060114.htm>



Headquarters

RIGOL TECHNOLOGIES, INC.
No.156,Cai He Village,
Sha He Town,
Chang Ping District, Beijing,
102206 P.R.China
Tel:+86-10-80706688
Fax:+86-10-80705070
Email: support@rigol.com

USA

RIGOL TECHNOLOGIES,USA INC.
7401 First Place, Suite N
Oakwood Village
OH 44164, USA
Toll free: 877-4-RIGOL-1
Office: (440) 232-4488
Fax: (216)-754-8107
Email: info@rigol.com

EUROPE

RIGOL TECHNOLOGIES GmbH
Lindbergh str. 4
82178 Puchheim
Germany
Tel: 0049- 89/89418950
Email: info-europe@rigoltech.com