



Instrument Firmware Release Notes

Models

DM3068

Version Information

Released version: 01.01.00.01.10.00.00

Release Date: 03/09/2016

Compatibility

Compatible with earlier versions of the hardware

Change Log

Key:

E – Enhancements. Changes that add functionality

M – Modifications. Changes to improve performance on existing features

C – Cancellation. Removal of function or capability

*Note: Engineering change log is translated from engineering documentation

Version : 01.01.00.01.10.00.00		Date : 2016-03-09
1.	Remove the spaces before the READ? command returns the result of the measurement	M
2.	Whether READ? command returns the measurement results of the positive and negative, where increased in front of a symbol mark	M
3.	Modify over-range returned values	M
4.	Add a remote command to adjust beeper sound	E
5.	Add a remote command to modify *IDN? command response data	E
6.	Optimize USB recognition when frequently reconnecting	M
7.	Fixed Temperature deviation with sensor measurement	M

Version : 01.01.00.01.09.00.01		Date : 2015-06-03
1.	Fix bugs for NPLC set to 0.006	M
2.	Fix the bug of unit of Temperature	M
3.	Fix the LAN bugs	M
4.	Add some new commands for dynamic tests	E

Version : 01.01.00.01.08.00.01		Date : 2013-09-18
5.	Fix TRIG bugs	M
6.	Fix SCPI bugs for LAN configuration	M

Version : 01.01.00.01.07.00.03		Date : 2012-10-30
7.	SCPI commands for Sensor	E
8.	Options for DIODE measurement	E
9.	4WR mode for Thermistor	E
10.	Fix some bugs for CAP measurement.	M

End of Change Log History

For more information in North America, please go to rigolna.com, contact us directly at techsupport@rigol.com or call us toll free at **877-4-RIGOL-1**.

Rigol Technologies USA

10200 SW Allen Blvd, Suite C
 Beaverton, OR 97005
 877.474.4651



For more information in Europe, please go to rigol.eu, contact us directly at applications-europe@rigoltech.com or call us +49 89 89 41 895-0.

Rigol Technologies EU GmbH

Lindberghstr. 4

82178 Puchheim, Germany

+49 89 89 41 895 - 0